

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Dennis Ware Controller			
OGM	Steve Demczak Environmental Scientist III			

Inspection Report

Permit Number:	C0070006 PARTIAL		
Inspection Type:			
Inspection Date:	Wednesday, June 11, 2008		
Start Date/Time:	6/11/2008 2:00:00 PM		
End Date/Time:	6/11/2008 4:00:00 PM		
Last Inspection:	Tuesday, May 20, 2008		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny,70's

InspectionID Report Number: 1684

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

8,919.91	Total Permitted
113.34	Total Disturbed
113.34	Phase I
	Phase II
	Phase III

Mineral Ownership

Types of Operations ✓ Underground ✓ Federal Surface ✓ State ☐ Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issied.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Wednesday, June 18, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 11, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		V		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	V		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 11, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee has applied for Phase II bond release at the Plateau Mine. Staff had been to the site to inspect the reclaim area to determine if the area meeting Phase II requirements.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The permittee showed a diversions were erosion was starting. The permittee is taking action to correct the problem.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment from leaving the mine site. There was evidence of sediment leaving the mine site.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

10. Slides and Other Damage

No slides were noticed during the inspection.

13. Revegetation

Vegetation is growing on the reclaimed area.

18. Support Facilities, Utility Installations

No support facilities are located on the site.